

February 7, 2017

NEW PRODUCT RELEASE (No. 0229)

RE: DOT Turn Signals

<u>K&S No.</u>	<u>Description</u>
25-2301	KA # OEM 23037-0069, Front Right ZX-600 (05-06), ZX-636 (05-06), KLE-650 (07-08), ZR-750 (05-06), ZX-1000 (05)
25-2302	KA # OEM 23037-0058, Front Left ZX-600 (05-06), ZX-636 (05-06), KLE-650 (07-08), ZR-750 (05-06), ZX-1000 (05)
25-2303C	KA # OEM 23037-0146, Rear Right ZX-600R (09-12), ZX-1000E/F (08-10), ZX-1000R (16-17) ZX-1000S ABS (16-17)
25-2304C	KA # OEM 23037-0145, Rear Left ZX-600R (09-12), ZX-1000E/F (08-10), ZX-1000R (16-17) ZX-1000S ABS (16-17)
25-2305C	KA # OEM 23037-0135, Front Right KA # OEM 23037-0136, Rear Left KL-650E (08-17) FR/RL, ZX-600 (07-08) RL
25-2306C	KA # OEM 23037-0134, Front Left KA # OEM 23037-0124, Rear Right KL-650E (08-17) FL/RR, ZX-600 (07-08) RR
25-2333C	KA # OEM 23037-0236, Rear Right ER-650C (09-10), EX-650C (09-11), EX-650E (12-14) EX-650F ABS (13-14), ZR-100D (10-13), ZX-1000G (11-13), ZX-1000H ABS (12-13)
25-2334C	KA # OEM 23037-0243, Rear Left ER-650C (09-10), EX-650C (09-11), EX-650E (12-14) EX-650F ABS (13-14), ZR-100D (10-13), ZX-1000G (11-13), ZX-1000H ABS (12-13)
25-3305	SU # OEM 35601-08J01, Front Right DL-650A (12-16), DL-650XA (15), GSX-S750 (15-16), GSX-S1000 F/FA (16)
25-3306	SU # OEM 35602-08J01, Front Left DL-650A (12-16), DL-650XA (15), GSX-S750 (15-16), GSX-S1000 F/FA (16)

New Product Release No. 0229

