

February 08, 2017

NEW PRODUCT RELEASE (No. 0228)

RE: DOT Turn Signals

(1) Product Information:

<u>K&S No.</u>	<u>Description</u>	
25-1311	HO # OEM 33400-MEG-670/305, Front Right VT-750C (04-09, 11-16), VT-750CA (04-09, 12-14) VT-750CS (13-16) **(Replacement Lens 25-1250, Replacement Bulb 25-8057)	MSRP: \$ 30.95
25-1312	HO # OEM 33450-MEG-670/305, Front Left VT-750C (04-09, 11-16), VT-750CA (04-09, 12-14) VT-750CS (13-16) **(Replacement Lens 25-1250, Replacement Bulb 25-8057)	MSRP: \$ 30.95
25-3261	SU # OEM 35601-27G00, Front Right DL-650 (04-08), DL-650A (07-08), DL-1000 (04-06) ** (Replacement Lens 25-3170, Replacement Bulb 25-8057)	MSRP: \$ 42.95
25-3262	SU # OEM 35602-27G00, Front Left DL-650 (04-08), DL-650A (07-08), DL-1000 (04-06) ** (Replacement Lens 25-3170, Replacement Bulb 25-8057)	MSRP: \$ 42.95
25-3263	SU # OEM 35603-06G10, Rear Right DL-1000 (04-06) ** (Replacement Lens 25-3170, Replacement Bulb 25-8057)	MSRP: \$ 42.95
25-3264	SU # OEM 35604-06G10, Rear Left DL-1000 (04-06) ** (Replacement Lens 25-3170, Replacement Bulb 25-8057)	MSRP: \$ 42.95

New Product Release No. 0228c



K&S Stock # 25-1311 Front Right



K&S Stock # 25-1312 Front Left



K&S Stock # 25-3261 Front Right



K&S Stock # 25-3262 Front Left



K&S Stock # 25-3263 Rear Right



K&S Stock # 25-3264 Rear Left



NOTE:
25-3261, 25-3262, 25-3263, 25-3264
have wire connectors instead of terminals