


August 19, 2011

NEW PRODUCT RELEASE (No. 0162)

RE: DOT Turn Signals for Suzuki's



(1) Product Information:

<u>K&S No.</u>	<u>Description</u>
25-3241	SU # OEM 35601-41FC0, Front Right VL-800 / C/ T "Blvd C50" (07-08, 11), VLR-1800 /T "Blvd C109R" (08-09)
25-3242	SU # OEM 35602-41FC0, Front Left VL-800 / C/ T "Blvd C50" (07-08, 11), VLR-1800 /T "Blvd C109R" (08-09)
25-3243	SU # OEM 35603-38AC1, Rear Right VL-800 "Volusa" (04-08), VL-800Z "Volusa LE" (04-05) VL-800 C/ T "Blvd C50" (06-08)
25-3244	SU # OEM 35604-38AC1, Rear Left VL-800 "Volusa" (04-08), VL-800Z "Volusa LE" (04-05) VL-800 C/ T "Blvd C50" (06-08)

(2) Packaging: Each piece is in bubble pack with an attractive back card.

